

May 23, 2018

Erik Wilson
City of Plainwell
211 North Main St.
Plainwell, MI 49080
ewilson@plainwell.org

RE: Production Well Water Sampling Results

Dear Erik:

Attached is the laboratory report from a sample we recently collected from three of your production wells. The samples were analyzed by Pace Laboratories. The samples were un-treated groundwater collected from a copper fitting inside each production wells well house. All three samples did not detect 2,3,7,8-TCDD (2,3,7,8-Tetrachlorodibenzo-p-dioxin) The laboratory report is summarized below.

Summary of Laboratory Results	
Sample	2,3,7,8-TCDD
PW #4	ND (Non-Detect)
PW #5	ND (Non-Detect)
PW #7	ND (Non-Detect)

Thank you for using the services of F&V. If you need additional information, please contact me.

Sincerely,
FLEIS & VANDENBRINK



Brian L. Rice, P.E.
Manager, Environmental Services Group

att: Laboratory Report and Chain of Custody
cc: Mark Worrall, MDEQ
Karen Vorce, MDEQ